

MG Trophy Championship Technical Specification GZR/0002



The two bolts shown need to be drilled 2.5 mm dia to take an MG Trophy seal.

It is strongly recommended that your gearbox is sent our Approved Gearbox Service specialists CMC Motorsport :-

CMC Motorsport
Unit 17M
MIRA
Nuneaton
Warwicks
CV10 0TU
Contact Dan SurrIDGE 07899 925454
dansurridge@cmcmotorsport.co.uk

A full inspection and check will be made and all ratios will be confirmed to be as per the latest regulations, any remedial work will also be undertaken, a charge will be made for this.

A record will be maintained of all seal numbers applied by CMC Motorsport, confirming the compliance with the latest regulations of that Gearbox. **If you decide to do this work yourself and the gearbox is subsequently found to be non compliant you will be penalised as per the current MG Trophy Championship regulations SR 4.**